

Mercedes Benz 312D 10,4 m3 Sprinter

Interna reparationer HEZ 817		
Ordernr	Datum	Beskrivning
SER000503	2001-12-06	AO 34.HEZ 817 SERVICE
SER001148	2001-12-02	DIESEL HEZ - 339
SER001217	2002-01-19	HEZ 817 BYTE DÄCK,AVLASTNING
SER004121	2002-04-13	DIESEL HEZ-817 21/11--18/2
SER008107	2002-08-29	HEZ817
SER009100	2002-10-10	HEZ 817
SER011251	2002-12-05	HEZ 817
SER012136	2003-03-26	HEZ 817
SER012766	2003-01-18	BEST.AV
SER012781	2003-01-18	BEST.AV
SER013074	2003-02-13	HÄMT.AV GERT
SER015296	2003-04-12	SERVICESATS MOTOR
SER015683	2003-05-14	BYTE DÄCK HEZ-817
SER017569	2003-06-24	VERKTYG
SER017735	2003-11-18	SERVICEBIL HEZ 817
SER022541	2003-11-26	GLÖDLAMPA
SER022707	2003-12-06	HEZ 817 REP & SERVICE
SER022707	2004-01-17	HEZ 817 REP & SERVICE
SER022707	2004-06-12	HEZ 817 REP & SERVICE
SER022707	2004-09-18	HEZ 817 REP & SERVICE
SER022707	2004-10-15	HEZ 817 REP & SERVICE
SER022707	2004-11-13	HEZ 817 REP & SERVICE
SER022707	2004-12-01	HEZ 817 REP & SERVICE
SER022715	2003-11-28	AVH.AV
SER027249	2004-05-19	HEZ817
SER035677	2005-05-13	SERVICE
SER035677	2005-05-13	SERVICE
SER036321	2005-05-24	HEZ 817
SER036584	2005-06-08	30/3 - 8/6-05
SER039818	2005-11-12	BES+UNDERHÅLL
SER039818	2005-12-03	BES+UNDERHÅLL
SER039818	2006-01-21	BES+UNDERHÅLL
SER039818	2006-04-22	BES+UNDERHÅLL,HEZ 817
SER039818	2006-05-20	BES+UNDERHÅLL,HEZ 817
SER048119	2007-01-15	DIV REP
SER049703	2007-04-16	SERVICE
SER057531	2008-04-30	DIV ARBETE
SER062189	2008-12-22	BYTE AV GENERATOR
SER063307	2009-03-16	DIV REP
SER067296	2009-10-26	DIV REP
SER069006	2010-02-15	DIV REP
SER070089	2010-04-29	DIV REP
SER072726	2010-10-11	DIV. REP.
SER079491	2011-12-19	DIV REP
SER082264	2012-09-04	DIV REP
SER083576	2013-01-21	DIV ARBETE